November 19, 2020

Index

Ed Service Center Cover

MEP #1 at Sterling HS Cover

EF Green JS 2
San Jacinto ES 3
Elementary 17 3

Lee Auditorium 2

Projects' Status 4

Education Service Center

Project Notes:

- · Restroom finishes are being installed
- Fitness Center lockers are being installed
- Finishes are being installed in the Wellness Center
- Workout equipment has been inspected and prepared for installation



Fitness Center Restroom and Showers

PBK

Comex Construction

MEP #1 at Sterling H.S.

Project Notes:

- Installed new gas line and foundation for generator
- Installing finish cap on the roof roof is 90% complete
- Continuing work on hydronic piping on roof
- Phase 2 work scheduled to be completed after Thanksgiving



Generator Pad

GCCISD

Facilities Planning and Construction

LAN

Program Managers



EMA Engineering

Bartlett Cocke Construction



Lee H.S. Armstrong Auditorium

Project Notes:

- Construction of ticket booth walls has begun
- Final polish of terrazzo is occurring
- Upgrades to rigging system underway



Ticket Booth Construction

Huckabee

Comex Construction

E.F. Green J.S.

Project Notes:

- Poured 2nd floor slab for buildings A & B
- Finished erection of cafeteria steel
- Framing began on exterior of building D
- Continuing 1st floor and 2nd floor MEP rough-in at buildings A & B



Exterior Framing of Building D

Pfluger Architects

Pogue Construction

San Jacinto Elementary

Project Notes:

- Proof rolling of soil is underway at building pad
- Demolition of the Beverage Barn is underway
- Site excavation continues for detention pond



Building Pad

PBK Marshall Construction

Elementary School #17

Project Notes:

- Site clearing is underway
- · Proof rolling of soil is underway at building pad
- Underground site utility work has begun



Building Pad

PBK

Drymalla Construction

Projects' Status

Site Improvements

· Administration will request endorsement for additional funding

Junior School Running Tracks

- Contract negotiation underway with contractor
- Administration will request endorsement for additional funding

SCTHS Phase 4

- General contractor has mobilized on site and construction fencing has been installed
- Permit has been issued
- Excavation and rough-grading is underway at building pad

Districtwide MEP #2

- System shut down and valve installation continues at DeZavala Elementary School
- Metered faucet installation progresses at Lee High School
- Awaiting delivery of remaining chillers in December

Districtwide Roof Replacement

• 100 % Construction Documents to be finalized by November

