ond Intermittent Report

#### Index

San Jacinto ES

Pumphrey ES

JS Running

MEP #1 at

Sterling HS

Projects' Status 3

Tracks

Cover

Cover

2

2

# San Jacinto Elementary

#### **Project Notes:**

- Polished concrete and carpet install continues
- Ceramic tile wainscot install continues at corridor
- Site grading is underway at South end and outdoor learning spaces
- Masonry work at main entry near completion
- Painting throughout building interior continues



Finishes installed at classroom

## PBK

## Marshall Construction

February 17, 2022

# **Pumphrey Elementary**

## **Project Notes:**

- Polished concrete and carpet install continues
- Terrazzo flooring complete at Rotunda area
- Early Learning Academy work continues
- Plumbing fixtures being installed throughout building
- Epoxy flooring installation is underway in the Kitchen



Terrazzo floor complete in Rotunda

GCCISD Facilities Planning and Construction

LAN Program Managers



PBK

**Drymalla Construction** 

#### Page 2



# **Junior School Running Tracks**

#### **Project Notes:**

- Track lane striping complete at Baytown
  Junior School
- Gentry JS, Horace Mann JS, Cedar Bayou JS, and Highlands JS all substantially complete



Lane striping complete at Baytown JS

#### **PBK Sports**

# MEP **#1** at Sterling H.S.

#### **Project Notes:**

- Ceramic tile installed in restrooms
- Fire Sprinkler installation continues
- Tape and float of gypsum at ceiling ongoing
- IDF room primed and ready for paint
- Above-ceiling inspection at phase 6 underway



Ceramic tile complete in restrooms

#### **EMA Engineering**

**Bartlett Cocke Construction** 

#### **Athletic Field Specialists**

# **Projects' Status**

Bond

#### **Districtwide Roof Replacement - Phase 2**

- Final pricing has been submitted to the District for review
- Project to be awarded to selected contractors by the end of the month

# Lee High School & Gentry Junior School Fine Arts Project

- General contractor has mobilized at Lee High School and Gentry Junior School
- Product submittals are being processed for review by the design team

## **Education Service Center - Phase 2 Project**

- Design team finalizing exterior renderings for administration approval
- Topographical survey and geotechnical reports are in progress

